



8/29/2022

UMC Cable assembly Discontinuation/ Replacement Notification

This letter serves as formal notification for the obsolescence of the Low Profile UMC cable assemblies when inventory is depleted. Effective immediately, the recommended replacement is the Medium profile UMC cable assemblies.

Discontinued Part Number	2.0mm Mating Height (Low Profile)	Recommended Replacement Part Number	2.5mm Mating Height (Medium Profile)
415-0084-050	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-050	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-100	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-100	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-150	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-150	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-200	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-200	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-250	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-250	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-300	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-300	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0084-500	UMC MATING CABLE PL 2.0mm MATING HT .81mm CABLE O.D	415-0085-500	UMC MATING CABLE PL 2.5mm MATING HT .81mm CABLE O.D
415-0089-150	CABLE ASSY,UMC.079(2.0mm) MATING HT.SMA STR PL.032	415-0090-150	CABLE ASSY,UMC.098(2.5mm) MATING HT.SMA STR PL.032
415-0089-250	CABLE ASSY,UMC.079(2.0mm) MATING HT.SMA STR PL.032	415-0090-250	CABLE ASSY,UMC.098(2.5mm) MATING HT.SMA STR PL.032
415-0092-150	CABLE ASSY,UMC.079(2.0mm) MATING HT. STR PL RP .032	415-0093-150	CABLE ASSY,UMC.098(2.5mm) MATING HT. STR PL RP .032
415-0092-250	CABLE ASSY,UMC.079(2.0mm) MATING HT. STR PL RP .032	415-0093-250	CABLE ASSY,UMC.098(2.5mm) MATING HT. STR PL RP .032
415-0095-150	CABLE ASSY,UMC.079(2.0mm) MATING HT.SMA BKHD J .032	415-0096-150	CABLE ASSY,UMC.098(2.5mm) MATING HT.SMA BKHD J .032
415-0095-250	CABLE ASSY,UMC.079(2.0mm) MATING HT.SMA BKHD J .032	415-0096-250	CABLE ASSY,UMC.098(2.5mm) MATING HT.SMA BKHD J .032
415-0098-150	CABLE ASSY,UMC.079(2.0mm) MATING HT.BKHD JK RP .032	415-0099-150	CABLE ASSY,UMC.098(2.5mm) MATING HT.BKHD JK RP .032
415-0098-250	CABLE ASSY,UMC.079(2.0mm) MATING HT.BKHD JK RP .032	415-0099-250	CABLE ASSY,UMC.098(2.5mm) MATING HT.BKHD JK RP .032
415-0101-150	CABLE ASSY,UMC.079(2.0mm) MATING HT.MMCX RA PL .032	415-0102-150	CABLE ASSY,UMC.098(2.5mm) MATING HT.MMCX RA PL .032
415-0101-250	CABLE ASSY,UMC.079(2.0mm) MATING HT.MMCX RA PL .032	415-0102-250	CABLE ASSY,UMC.098(2.5mm) MATING HT.MMCX RA PL .032
415-0104-150	CABLE ASSY,UMC.079(2.0mm) MATING HT TO BARE END.032	415-0105-150	CABLE ASSY,UMC.098(2.5mm) MATING HT TO BARE END.032
415-0104-250	CABLE ASSY,UMC.079(2.0mm) MATING HT TO BARE END.032	415-0105-250	CABLE ASSY,UMC.098(2.5mm) MATING HT TO BARE END.032

Thank you for your understanding in this matter. Should you have any questions, please contact your local Cinch Sales Representative or Customer Service Representative at (800) 247-8256.

Cinch Connectivity Solutions appreciates and values our business relationship and looks forward to your continued interest in our products. While we regret any inconvenience this announcement may cause, we are eager to supply your future product requirements with our world-class quality product portfolio.

Regards,

*Ketan Thakkar*

Ketan Thakkar

Sr. Product Manager – Johnson Product Line

1700 Finley Road  
Lombard, IL 60148 USA

T +1 630.705.6000  
[belfuse.com/cinch](http://belfuse.com/cinch)

