



January 28, 2008

### Cinch Authorized Distributors

Due to tooling issues Cinch can no longer produce the 30 position 300 series Jones plug & socket. Effective immediately the part numbers listed below are discontinued. Please make the appropriate changes in your system. If you have any of the discontinued part numbers in your system you have 30 days to request an RMA. Please note the parts need to be in good condition and purchased within the last two years from Cinch.

|            |            |
|------------|------------|
| P-330-AB   | S-330-AB   |
| P-330-LAB  | S-330-LAB  |
| P-330-DB   | S-330-DB   |
| P-330-CCE  | S-330-CCE  |
| P-330-CCT  | S-330-CCT  |
| P-330-CCTL | S-330-CCTK |

Cinch is sorry for any inconvenience this may cause you or your customers.

Pam Bauch  
Cinch Connector  
Asst. Product Manager  
Commerical Products